

# Basic Repair Price List

Repair details		CA4LA products Price (incl. tax & processing fee)	Other brands Price (incl. tax & processing fee)
Ribbon replacement	Rayon grosgrain	¥2,200	¥4,400
	Italian ribbon (10/15/40mm width)	¥4,400	¥8,800
	Silk ribbon (40mm width)	¥5,500	¥11,000
	Patterned ribbon	¥4,400	¥8,800
	Imported three-layer ribbon	¥4,400	¥8,800
	Own ribbon brought in	¥2,200	¥4,400
	Own fabric ribbon/scarf brought in	From ¥13,200	From ¥26,400
Sweatband replacement	Sweatband size adjustment	From ¥4,400	From ¥8,800
	Grosgrain ribbon	From ¥4,400	From ¥8,800
	Leather sweatband	From ¥5,500	From ¥11,000
	Cotton sweatband	¥9,900	¥19,800
Reshaping	Steam	¥2,200	¥4,400
	Light reshaping / Brim lowering	¥3,300	¥6,600
	Heavy reshaping / Brim change	¥5,500	¥11,000
	Shape change	¥11,000	¥22,000
	With lining	Plus ¥1,100	Plus ¥2,200
Size expansion	Free (Fees apply to certain services)		

\*We also accept repairs not included in the price list, so please don't hesitate to contact us.

CA4LA

# Price List for Hat Bodies/Woven Hats

Repair details		CA4LA products Price (incl. tax & processing fee)	Other brands Price (incl. tax & processing fee)
Brim trimming	Partial trim	¥2,200	¥4,400
	Woven/raw edge	¥3,300	¥6,600
	Turn-back brim edge	¥4,400	¥8,800
Piping (wire insert)	Grosgrain	¥5,500	¥11,000
	Italian ribbon	¥7,700	¥15,400
	Silk ribbon	¥8,800	¥17,600
	Fabric	From ¥11,000	From ¥22,000
Wire replacement	Wire replacement	¥4,400	¥8,800
	Wire only	¥2,200	¥4,400
Braid hole repair	Up to half of the circumference (30cm)	¥2,200	¥4,400
	Full circumference	¥3,300	¥6,600
	More than the full circumference (every 30cm)	Plus ¥2,200	Plus ¥4,400
Cracked straw hat body (one area)		¥2,200	¥4,400
Lining replacement		¥11,000	¥22,000
Lining attachment	Sewn on	¥2,200	¥4,400
	Attached with glue	Free	¥1,100

\*We also accept repairs not included in the price list, so please don't hesitate to contact us.

CA4LA

# Price List for Caps, Fabric Hats, and Knitted Caps

Repair details		CA4LA products Price (incl. tax & processing fee)	Other brands Price (incl. tax & processing fee)
Top button repair	Fabric in stock	¥2,200	¥4,400
	Fabric ordered in	¥5,500	¥11,000
Cap adjuster replacement	Plastic	¥2,200	¥4,400
	Leather	¥3,300	¥6,600
	Replacement of metal parts	¥2,200	¥4,400
Brim replacement		¥11,000	¥22,000
Panel replacement for a six-panel cap (one panel)		¥33,000	¥66,000
Inserting elastic into a knitted cap		¥2,200	¥4,400

\*We also accept repairs not included in the price list, so please don't hesitate to contact us.

# Price List for Embellishments

Repair details		CA4LA products Price (incl. tax & processing fee)	Other brands Price (incl. tax & processing fee)
Comb attachment	10 prongs (2 combs)	¥1,650	¥1,650
	18 prongs (1 comb)	¥2,200	¥4,400
Chin strap (elastic)		¥110	¥110
Embellishment removal	Removal only	Free	Not accepted
	Removal and touch-up	¥2,200	¥4,400
Veil attachment		From ¥8,800	From ¥17,600
Tulle replacement		¥8,800	From ¥17,600

\*We also accept repairs not included in the price list, so please don't hesitate to contact us.